



Errata

NFPA 70[®]

National Electrical Code[®]

2017 Edition

Reference: 300.4, Informational Note, and Table 310.104(A)

Errata No: 70-17-1

Code-Making Panel 3, Code-Making Panel 6, and the Correlating Committee on National Electrical Code note the following errors in the 2017 edition of NFPA 70[®], *National Electrical Code*[®].

1. Delete the Informational Note to 300.4:

~~Informational Note: Minor damage to a raceway, cable armor, or cable insulation does not necessarily violate the integrity of either the contained conductors or the conductors' insulation.~~

2. In Table 310.104(A), Moisture-resistant thermoplastic, add a missing "0" (zero) to the first entry in the "mils" column to read as follows:

Table 310.104(A) Continued

Trade Name	Type Letter	Maximum Operating Temperature	Application Provisions	Insulation	Thickness of Insulation			Outer Covering ²
					AWG or kcmil	mm	mils	
Moisture-resistant thermoplastic	TW	60° C (140° F)	Dry and wet locations	Flame-retardant, moisture-resistant thermoplastic	14-10	0.76	30	None
					8	1.14	45	
					6-2	1.52	60	
					1-4/0	2.03	80	
					213-500	2.41	95	
					501-1000	2.79	110	
					1001-2000	3.18	125	

Issue Date: September 29, 2016

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/docinfo)